

Step2®
Whisper Ride Touring Wagon
Model No. 832900
Fall Hazard



**PLEASE IMMEDIATELY STOP USING THE
WAGON**

Affected wagons have seat belts that are connected to the blue seat backs. Wagons that include seat belts connected to the tan wagon base are not included in this recall.

**Contact Step2® toll-free at (866) 860-1887 between 8 a.m. and 5 p.m. EST Monday through Friday
or
visit the firm's Web site at www.step2.com
To receive a free repair kit.**